Braden PRINTING INC.

Inches to Decimal Conversion Chart

Ruler enlarged to view 1/2 inch

0	
1/64	= .015625
1/32	= .03125
3/64	= .046875
1/16	= .0625
5/64	= .078125
3/32	= .09375
7/64	= .109375
1/8	= .125
9/64	= .140625
5/32	= .15625
11/64	= .171875
3/16	= .1875
13/64	= .203125
7/32	= .21875
15/64	= .234375
1/4	= .25
17/64	= .265625
9/32	= .28125
19/64	= .296875
5/16	= .3125
21/64	= .328125
11/32	= .34375
23/64	= .359375
3/8	= .375
25/64	= .390625
13/32	= .40625
27/64	= .421875
7/16	= .4375
29/64	= .453125
15/32	= .46875
31/64	= .484375
1/2	= .5

Ruler enlarged to view 1/2 inch

33/64	= .515625
17/32	= .53125
35/64	= .546875
9/16	= .5625
37/64	= .578125
19/32	= .59375
39/64	= .609375
5/8	= .625
41/64	= .640625
21/32	= .65625
43/64	= .671875
11/16	= .6875
45/64	= .703125
23/32	= .71875
47/64	= .734375
3/4	= .75
49/64	= .765625
25/32	= .78125
51/64	= .796875
13/16	= .8125
53/64	= .828125
27/32	= .84375
55/64	= .859375
7/8	= .875
57/64	= .890625
29/32	= .90625
59/64	= .921875
15/16	= .9375
61/64	= .953125
31/32	= .96875
63/64	= .984375
1	=1.0

1 Pica = 12 Points 6 Picas = approximately 1 Inch (.9936 Inch) 1 Point = .0138
1 Inch = 14 Agates 1 Inch = 2.54 Centimeters 1 Inch = 25.4 Millimeters

19 Ralston St. • PO Box 571 • Keene, New Hampshire 03431 • 603-357-1513 • NH WATS 800-750-1513 • FAX 603-352-3262
Email: customerservice@bradenprint.com • Web Site: www.bradenprint.com

© 1999 Braden Printing Inc. This information is freely provided as a service to our customers, compiled from our experience and/or industry sources. While we make reasonable effort to check the accuracy of this information, we present it without warranty of any kind and accept no liability of any kind for its use.